



- A. 49-64
- B. AFC-121
- C. 122-4
- D. 11A28 (ADJUSTABLE)
11A27 (NON ADJUSTABLE)
- E. 49-64-P41-66 (3/8" COOLANT FITTING)
- F. WATER JACKET 180°, 90° AND 45°
CALL FOR QUOTE
- G. 54-86 (3/8" SAE FLARE)
55-8 (1/2" SAE FLARE)
- H. 721019 (OEM NLA, REPLACE WITH
NF721019)



- A. 49-64
- B. AFC-121
- C. 122-4
- D. 11A28 (ADJUSTABLE)
11A27 (NON ADJUSTABLE)
- E. 49-64-P41-66 (3/8" COOLANT FITTING)
- F. WATER JACKET 180°, 90° AND 45°
CALL FOR QUOTE
- G. 110-86-116-6-48-66 (3/8" SAE FLARE)
110-86-116-6-48-86 (1/2" SAE FLARE)
- H. NF721019 (DIRECT REPLACEMENT
FOR ORIGINAL 721019)



The modified regulator (NF721019) acts as an easy to install replacement that will allow the machine to continue to operate without replacing any other components. Rebuild kits are also readily available for the NF721019.

