FOR INSTALLATION OF THE TRANSFER KIT REMOVE THIS CAP, THERE SHOULD BE NO POSITIVE FLOW, THESE HAVE CHECK VALVES BUILT IN

7572FC (3/4" NGT) OLD STYLE 7590U (1-5/8"UNF) NEW STYLE





NEVER REMOVE THIS VALVE